

Slide notes: The Job Master is directly accessible from the Planned Maintenance Menu, because each Maintenance Master is a Job.

ES Client(Q) v8.7	15 : My IES Stars Conneck					U.C.C.
() — ()	9	0 (0	« »	-	(9)	(z) (X)
1.Man 2.M	aligence 20abjets					
				🛗 🕕 🕯	🔐 😎 速	-
anter anteres Secondor Anteres	KILUX 2000, KOKIOL		Cest Type Process Last Types 1	Auto Debit	Auto Credit	1
Internal Manag	enient	initianit.				
( participante ( participante) ( participante)	07EN		Ladare filleration			Sanci
Presit lines Supervised	GEC 109 FLEET OFERATIONS		Funced Dabit	-	Forced Credits	1
	C Accept Hanufacture Re-Olarges 1 Use A Weler?					
ingui hati () ingui hati () ingui hati ()	0 0 Jea					Ĵ
Continuer Order Carl Draw to Drawtor	Roberence		<u>e</u>	Last sparse Last sparse		ail I



MES Client(Q) v8.7	25 - My IES					L.I.C.
()	0	0 (0	a n		(*)	(2) (X)
1.Wen 214	allgaren 3.Dubgeta					
				ີ ພະ 🕘 າ	🕹 😎 🕹	
All here and encounter Tenangement	REFERS 5000' REGRIDE		Cost Type Processis East Types 1	Auto Debit	Auto Credit	1
CERTIFIC		munt	I			
Intensal Manay	OPEN		-			-
Cherrological			Ledger Allocative			2000
Course Charger	109 FLEET OPERATIONS		Furced Debits		Forced Coefficts	Î
	C Accept Manufacture Re-Charges 1 Libe & Meler 1					
i terri hisi g	0		-			1
Table 110	ka					
Centemor Order Cert Draw to Deather	Reference	Re .	0	Latrante Latra		



⊢ ()	9	0 (Q	« »	-	(*)	e
1.Wein 2.H	Nigeran 3 Dalgeta					
				<b>***</b>	r 🐨 🛓	
	VEH1353 (2012)1 FULUX 2000, ECH301 LOV LOV:8		Cost Type Processing Don't Types 3 148 1abor 4 RAT Reterial	Auto Dabit 1D-50-00-65 FLEET EX 1D-50-00-65 FLEET EX	Auto Credit	
Internal Manag	enient ofen	initianit.	5 011 011 6 FLF FLE Fure 7 FLF FLE Serv 8 FLE FLE Stor	10-90-00-65 FLET EX 10-10-10-292 FL MAIN 10-10-10-293 FL MAIN 10-10-10-293 FL MAIN		
Dest Caseson Dest Connection Dest Connection Connect Connect	LOS PARET OPERATIONS		Ledger Allocative Forced Debits		Ponced Coeffictor	0.000
	Accept Manufacture Re-Charges 1 Live A Weler 1			_		
ingui hoto gi insuest hoto insuest hoto	0 0 Jen					
Costrante Orde Carl Scorito	c Roberence	5	10	Lad the first		

Slide notes: We can define a new Job here, but usually the Job already exists, and when we include it on the Planned Maintenance Master, then we need to ensure that it has the Cost Types listed, with the required auto Debit Accounts, as specified for the Planned Maintenance operation. Note here the 3 Cost Types for Planned Maintenance.









IES Client(Q) v8.7 so subnit Quit Ru	25 : My IES actions Commands					Lule
1.Wain 21d	eligence: 20.appla		« »			
				<b>***</b>	7 🕹	
	VEH1351 100010511 HELUX 2000, HORIOL LOV LOV'8		Cest Type Processing East Types 3 148 1abot 4 Mat Reterint 5 031 031	Auto Debit ID-90-00-65 FLEET EX ID-90-00-65 FLEET EX ID-90-00-65 FLEET EX	Auto Credit	
Intensal Manag	ement OPER	intanti	5 FLF FLE Furt 7 FLE FLE Serv 8 FLE FLE Stor 1 FLE FLE Stor	10-10-10-292 P1 MAIN 10-10-10-293 P1 MAIN 10-10-10-293 P1 MAIN 10-10-10-291 P1 MAIN	- -	Balart
Charge Colonial Present Resources Colonies Chargers	LDV LOS FLEET OFERATIONS		Ledger Allocation Funced Debits	-	Forced Creffits	
	Accept Manufacture Re-Charges 1 Use A Webs?	K.		_		
Territoria Consultant Vision CO	0 0 Jea		-			
Cestemer Order Cert provins Denter	Reference	No.		Last teacher Last teacher		

Slide notes: We do not discuss the full procedure for opening a new Job here. That is available in the Job Costing tutorials. The important point to note is that we need to have the correct Cost Types listed for Maintenance.



Slide notes: Let us quickly look at the Control Parameters for Planned Maintenance.

IES Client(Q) v8.25 : Ny IES Heb Subrit: Out Functions Commands		
⊳ 0 Q	• • • • •	(4) (2) (X)
		Sang
	Processing of non-Stock Costs Julia Process Service Costs Auto Process Sills Costs	
for fact that the force to come	Joh Cest Types to apply for Chargest PLS PLB Stock p1: PLB Securices p1p PLB Furcheeing	
t		

Slide notes: And here we can see the Cost Types specified for Planned Maintenance charges. So these are the Cost Types that we need to include for all Jobs that we list on the Planned Maintenance Master, in addition to any other Cost Types used on these Jobs already.

Market Schentifle) v8.25 My IES Help Subnit Out Functions Connends		
⊳ 0 Q	с 0 с » т I	() (2) (3)
		.Bana
	Processing of non-Stock Contu-	
	Audo Proceso Salat Costo Audo Proceso Salat Costo	
c e e e e e e e e e e e e e e e e e e e	Job Cest Types to apply for Changes: .	
Section Inc.	PLS FUE Stude plx FUE Services	
Call Fact Processed	pip flØ furchesing	
-		
E		

Slide 10 Slide notes:

Market Schentifle) v8.25 My IES Help Subrit Out Functions Commands		
⊳ 0 Q	○ ○ ○ ○ □ □	() (A (A)
		.Care
	Processing of non-Stock Contra-	
	Paulo Process Service Costs Aulo Process Selle Costs	
	Job Cest Types to apply for Changes:	
Der Tass. Smith	PLA PLE Stock	
Katt Fred Pressenter	pip res recouring	
E		

