



Slide 1


Slide notes: A Master Listing of the Planned Maintenance Master is offered for OPEN Maintenance Items and CLOSED ones. We will now look at an example of the OPEN Master Items.













Slide 5 Slide notes:

🝺 Q1544131627A.TXT - Notepad		
File Edit Fornet View Help		
Înfolab (Fty) İti		
09:47:07 10 APR 2010 page 1		
Flarmed Haintenance Harter		
Key. feqc002	Description. Conveyor Chain	Ryment Group. FH Pactory Hachinery
fegc002	Transmission Chain # 3	[fn] Factory Hachinery
VIH1902	CHERRY 1400, D6D202	(VECHE) Vehicle Service: Cherry
VERI 901	HANDA 1600, AAR107	(VSHAW) Vehicle Service: Hamia
VEHI 905	HANDA 1600, B0D604	(vshan) Vehicle Service: Handa
vehi904	HANDA 1600, HOH444	(vshan) Vehicle Service: Handa
VERI 902	HANDA 1600, W00192	(vshan) Vehicle Service: Handa
vehi269	RILAIN 2000, ARD:544	[vw] Vehicle Service: Filux
vehi262	WILMEN 2000, CDE201	[VB] Vehicle Service: Filur
VERI 262	MILMIN 2000, 3C5424	[vw] Vehicle Service: Rilux
VEHL270	MILMIN 2000, JJ1529	[vm] Vehicle Service: Rilur
vehi252	MILMIN 2000, INGLESS	[vm] Vehicle Service: Rilux
VERI 269	MILMIN 2000, MEMORY	[vw] Vehicle Service: Filux
VERI 256	KILSEN 2000, KLL122	[vw] Vehicle Service: Filux
VEHL257	MILMIN 2000, ML1989	[vw] Vehicle Service: Filux
VERI 251	MILMIN 2000, MOREOL	[vw] Vehicle Service: Filux
vehi252	MILMIN 2000, MORNOS	(vw) Vehicle Service: Kilux
vehi250	MILMIN 2000, MORGES	vz Vehicle Service: Riluz
VERI 266	MILMIN 2000, MOR936	(vs) Vehicle Service: Rilus
VERI 264	MILLIN 2000, LHHLEOO	[vw] Vehicle Service: Rilux
VERLOSS	WILMIN 2000, 000393	[vw] Vehicle Service: Rilux
VERI 259	KILUX 2000, STERES	vr Vehicle Service: Kilur

Slide 6

Slide notes: This is an example of the Report, which is Version friendly and that means that we are able to change the Report any way we like, and to include different columns, to sort in a preferred way, etc.